



SL-T0603IRC020-L98 DATA SHEET

 SPEC. NO.
 : SZ21062901

 DATE
 : 2021/06/29

 REV.
 : A/0

Approved By: Checked By: Prepared By:

Part No.	SL-T0603IRC020-L98	Page	1 of 9
----------	--------------------	------	--------






Features

Pb free product—RoHS compliant Low power consumption, High efficiency Reliable and rugged Long life – solid state reliability Good spectral matching to Si photo detector

Package Dimension



Part NO.	Source Color	Lens Color
SL-T0603IRC020-L98	Infrared	Water Clear

Notes:

- 1. All dimensions are in millimeters.
- 2. Tolerance is ± 0.10 mm unless otherwise noted.
- 3. Specifications are subject to change without notice.

Part No.	SL-T0603IRC020-L98	Page	2 of 9
----------	--------------------	------	--------



LIGHT ELECTRONICS CO., LTD.



Absolute Maximum Ratings at Ta=25

Parameter	MAX.	Unit	
Power Dissipation	100	mW	
Continuous Forward Current	60	mA	
Peak Forward Current*2	400	mA	
Reverse Voltage	5	V	
Electrostatic Discharge (HBM)*3	4000	V	
Moisture Sensitivity Level*1	4		
Operating Temperature	-40 to +85		
Storage Temperature	-40 to + 100		
Reflow Condition	260 MAX for 10 Seconds		

1. Storage and operating:

- (1). Storage requirements before vacuum bag opened: Temperature<30 , Humidity<65%RH;
- (2). Check air leakage and vacuum bag damage before opened. If there is any issue found, check the humidity indicator card immediately after bag opened:
 - a. If color changes on "10% circle" of the humidity indicator card only and not the circles of 20% and above, components can be used without additional handling;
 - b. If color changes on both 10% and 20% circles but not the circles of 30% and above, components must be dehumidified according to the conditions of bullet (5);
 - c. If color changes on 10%, 20%, and 30% circle or above, the product should be returned to the supplier for high temperature dehumidification;
- (3). After bag opened, manual soldering or reflow process must follow the following requirements:
 - a. Complete soldering / reflow within 72 hours;
 - b. Requirements of working environment: Temperature<30 , Humidity<60%RH;
- (4). If the working condition is outside (3)a requirement, the components must be dehumidified according to the conditions of bullet (5);
- (5). Low temperature dehumidification: temperature 60±5 , at least 24 hours;
- (6). Shelf life: 180 days. If it's over 180 days from the production date on the package label, the components must be dehumidified according to the condition of bullet (5). If customer is unable to dehumidify, return components to LIGHT for dehumidification.


2. Peak Forward Current:

Condition for is IFP pulse: Pulse Width 100us and duty 1%.

3. Caution in ESD:

Static Electricity and surge damages the LED. It is recommend to use a wrist band or anti-electrostatic glove when handling the LED. All devices, equipment and machinery must be properly grounded.

Part No.	SL-T0603IRC020-L98	Page	3 of 9
----------	--------------------	------	--------






LIGHT ELECTRONICS CO., LTD.



Typical Electrical / Optical Characteristics Curves

(25 Ambient Temperature Unless Otherwise Noted)



Part No. | SL-T0603IRC020-L98

Page

5 of 9



LIGHT ELECTRONICS CO., LTD.




Radiant Intensity Bin Code (I_F=20mA)

BIN CODE Min. (mW/sr) Max. (mW/sr)

24

 Part No.
 SL-T0603IRC020-L98
 Page
 6 of 9




LIG	LIGHT ELECTRONICS CO., LTD.		
Part No.	SL-T0603IRC020-L98	Page	8 of 9





Suggest IR Reflow Condition For Lead Free




- 1. Reflow soldering should not be done more than two times.
- 2. When soldering, do not put stress on the LEDs during heating.

Soldering iron

- 1. When hand soldering, the temperature of the iron must less than 300 for 3 seconds.
- 2. The hand solder should be done only once.

Repairing

Repair should not be done after the LEDs have been soldered. When repairing is unavoidable, a double-head soldering iron should be used (as below figure). It should be confirmed beforehand whether the characteristics of LEDs will or will not be damaged by repairing.



Part No. | SL-T0603IRC020-L98 | Page | 9 of 9